



Description: 3rd Brake Light
Part Number: 531097, 531098, 531099

Application: 2014 and up Chevy Silverado and GMC Sierra 1500, 2015 Chevy Silverado and GMC Sierra 2500,3500

Tools Needed
Torx Bit set
3/8 ratchet
Wire Crimpers
Wire connectors



Remove the 2 Torx screws
holding the light to the body.



Disconnect the plug from the light.



Once the light is removed from
the truck . Clean the surrounding
part of the cab so the new
gasket supplied with the light
can be applied to the vehicle.



We chose to cut the stock
connector off. You do not have
to. The wires get spliced in the
following sequence.
White to White
Red to Purple
Black to Black



Reinstall the light and test the
functions.

AnzoUSA™ products are covered, by a limited one (1) year warranty, to be free of manufacturer's defects. However, certain AnzoUSA™ product categories have warranty policies which differ from this standard, please contact your representative for detailed category information. Damage due to improper installation or road hazards is not covered. Seller and manufacturers' only obligations shall be to replace the product proven to be defective. Neither seller nor manufacturer shall be liable for any injury, loss or damage, direct or consequential, arising out of the use of or the inability to use the product. Before using, user shall determine the suitability of the product for its intended use, and user assumes all risk and liability whatsoever in connection therewith.